

Сводная таблица применяемости ГМЛ-П

Сечение, мм ²	Количество	1,0			1,5			2,5			4,0			6,0		
		1	2	3	1	2	3	1	2	3	1	2	3	1	2	3
1,0	1			6	6		6	6	6/10	10						
	2		6	6	6	6	6/10	6	10	10						
	3	6	6		6	6	10	6	10							
1,5	1	6	6	6		6	6/10	6	6/10	10	6					
	2		6	6	6	6/10	10	6/10	10	10/16	10	10				
	3	6	6/10	10	6/10	10	10	6/10	10	16	10	16	16			
2,5	1	6	6	6	6	6/10	6/10	6	10	10/16	10	10	16	10		
	2	6/10	10	10	6/10	10	10	10	10	16	10	16		16		
	3	10	10		10	10/16	16	10/16	16	16		16		16		
4,0	1				6	10	10	10	10		10		16			25
	2					10	16	10	16	16		16		16	25	
	3						16	16			16		25	16	25	
6,0	1							10	16	16		16	16			25
	2											25	25		25	
	3										25			25		